






		UNITED KINGDOM - CHINA - MALAYSIA	
Visual Inspection			
Crumbled to Dust!	Exploded in the Kiln!	Heated to 900°C	
		Heated to 600°C	
		Heated to 300°C	
2011	2012	Not Heated	











	UNITED KINGDOM - CHINA - MALAYSIA	
Additional Considerations		
<ul> <li>Angle and Distance</li> <li>Ambient Light</li> <li>Type of Laser</li> <li>Type of Concrete</li> <li>Paint on Concrete</li> </ul>		
Can Water Damage be Detected?		
FIG WORKING WEEK 2012		

